

Workorder Summary Report

Report Start Date: Mar 1, 2020 12:00 AM  
Report End Date: Mar 31, 2020 11:59 PM  
Location: 1103\*  
Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM  
Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
<a href="#">1657541</a>	0000227376	PANEL ALARM/ DIALER	1103, Fort Frances WPCP, Process, Process Control & Monitoring	PM	Inspection	1	MONTHS	Critical Alarm/Dialer Testing (1m) 1103	COMP	3/1/20 12:00 AM	3/31/20 08:56 AM	3/31/20 08:56 AM	Dialer Test -We test daily.
<a href="#">1657545</a>			1103, Fort Frances WPCP	PM	Refurbish/ Replace/Repair	1	MONTHS	Diesel Gensets Inspection/ Functional Tests (1m) 1103	COMP	3/1/20 12:00 AM	3/23/20 07:13 AM	3/23/20 07:13 AM	
<a href="#">1657561</a>			1103, Fort Frances WPCP	PM	Health and Safety	1	MONTHS	Health And Safety Inspection (1m) 1103	COMP	3/1/20 12:00 AM	3/31/20 08:57 AM	3/31/20 08:57 AM	H&S Monthly -No issues.
<a href="#">1657572</a>			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	TPM Inspection/Maintenance (1m) 1103	COMP	3/1/20 12:00 AM	4/2/20 02:35 PM	4/2/20 02:35 PM	
<a href="#">1657935</a>			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	Blowers/Motors Inspection/Service (1m/3m) 1103	COMP	3/1/20 12:00 AM	3/31/20 09:02 AM	3/31/20 09:02 AM	Monthly Blowers -I greased all blowers
<a href="#">1657945</a>	0000246402	CENTRIFUGE GS2-2-1 TEACUP/ GRIT SNAIL	1103, Fort Frances WPCP, Process, Primary Treatment, Primary Sludge Degritting	PM	Inspection	1	MONTHS	Teacup Centrifuge Inspection/ Service (1m/3m/1y) 1103	COMP	3/1/20 12:00 AM	3/23/20 12:02 PM	3/23/20 12:02 PM	Teacup Centrifuge Inspection/ Service (1m/3m/1y) 1103 -Drained and inspected teacup and Grit Snail. Removed a tiny bit of debris from Teacup and hosed Grit Snail. Greased bearings and lubricated drive chain.
<a href="#">1657962</a>			1103, Fort Frances WPCP	PM	Refurbish/ Replace/Repair	3	MONTHS	Clarifiers Inspection/Service (3m) 1103	COMP	3/1/20 12:00 AM	3/31/20 09:04 AM	3/31/20 09:04 AM	Clarifier Service -I greased the clarifier drives.
<a href="#">1658369</a>			1103, Fort Frances WPCP	PM	Inspection	6	MONTHS	UV Reactors Clean/Inspect/Bulb Replacements (6m) 1103	COMP	3/1/20 12:00 AM	3/6/20 10:56 AM	3/6/20 10:56 AM	UV Reactors Clean/Inspect/Bulb Replacements (6m) 1103 -All sleeves UV banks A, B and C were acid washed and the UV sensor bank B was replaced January 14, 2020
<a href="#">1661905</a>	0000246428	PUMP CENT BOUNDARY P1	1103, Boundary Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		Boundary P1 Fail 1103	COMP		3/4/20 01:42 PM	3/4/20 01:47 PM	Boundary Lift Station -Came in to assist Kelly for a wetwell entry and pull P1 pump to inspect.
<a href="#">1662431</a>	0000246414	TANK PROCESS CLARIFIER SECONDARY CELL #1	1103, Fort Frances WPCP, Process, Secondary Treatment	CALL	Refurbish/ Replace/Repair	0		Clarifier #1 Long Collector Failure 1103	COMP		3/8/20 03:01 PM	3/8/20 03:06 PM	Long Collector #1 Failure -I arrived onsite to find the shear pin to be broken so I replaced it and restarted it. I then kept the lid off to monitor and it seemed ok so I replaced the lid after 4 hours.

Workorder Summary Report

Report Start Date: Mar 1, 2020 12:00 AM

Report End Date: Mar 31, 2020 11:59 PM

Location: 1103\*

Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM

Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
<a href="#">1663460</a>			1103, Fort Frances WPCP	CALL	Refurbish/ Replace/Repair	0		Covid 19 Planning 1103	COMP		3/16/20 11:38 AM	3/16/20 11:43 AM	Covid 19 Planning -Brad called to discuss Covid 19 planning for plant going forward.
<a href="#">1663582</a>	0000227421	PUMP CENT VERTICAL NON CLOG SEWAGE P1 FIFTH ST	1103, 5th St. Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		Fith Street High Level Alarm 1103	COMP		3/17/20 03:30 PM	3/17/20 03:34 PM	Fifth Street High Level -I was called in to assist Kelly in a confined space entry at Fifth Street lift station to stop the pumps from airlocking .
<a href="#">1664426</a>	0000246436	PANEL CONTROL PCL	1103, Boundary Pumping Station, Facility	CALL	Refurbish/ Replace/Repair	0		Boundary Road fire alarm call in 1103	COMP		3/24/20 04:15 PM	3/24/20 05:30 PM	Boundary Road fire alarm call in 1103 - I was called by the auto dialer for a Boundary Road lift station fire alarm. I called Communique Action and drove to the plant where I acknowledged alarms on SCADA. The station appeared to be functioning so I drove there to physically verify. There were no issues so returned to the plant and closed my ticket. This can most certainly be blamed on a PLC glitch as there were several alarms that came in at the same time.
<a href="#">1664569</a>	0000246414	TANK PROCESS CLARIFIER SECONDARY CELL #1	1103, Fort Frances WPCP, Process, Secondary Treatment	CALL	Refurbish/ Replace/Repair	0		Collector Failure 1103	COMP		3/26/20 07:51 AM	3/26/20 07:56 AM	Collector Failure Alarm -Once I got to work I checked SCADA to find Long Collector #1 to be in fault due to a failed shear pin. After I replaced the shear pin I then monitored for 30 min and all was good.