

## Work Orders

| ID      | Asset ID | Department     | Work Order Type                | Work Order Subtype                 | Asset Name                         | Asset Location                        | Status    | Assigned To                 | Hours | All Notes  | Completed Date |
|---------|----------|----------------|--------------------------------|------------------------------------|------------------------------------|---------------------------------------|-----------|-----------------------------|-------|--|----------------|
| WO-2562 | 15251    | Com Serv - MSC | Preventative Maintenance - MSC | Filter/ Belt Inspection            | F-5 IFK Classroom Furnace          | IFK Second Floor Mechanical Room East | Completed | Bob Green                   |       |  | 2019-02-28     |
| WO-2557 | 15266    | Com Serv - MSC | Preventative Maintenance - MSC | Filter Backwash                    | Pool Sand Filters #2               | Main Floor Pool Mechanical Room       | Completed | Bob Green                   |       |  | 2019-02-27     |
| WO-2549 | 15250    | Com Serv - MSC | Preventative Maintenance - MSC | Filter/ Belt Inspection            | F-6 Front Door Airlock Furnace     | IFK Lobby Mechanical Room             | Completed | Crystal Tan                 |       | Need to replace monthly.   | 2019-02-13     |
| WO-2517 | 15254    | Com Serv - MSC | Preventative Maintenance - MSC | Filter/ Belt Inspection            | F-1 IFK Arena Furnace              | IFK Second Floor West Mechanical Room | Completed | Crystal Tan,<br>Jason Kabel |       | Crystal and Jason replaced the filters   | 2019-02-04     |
| WO-2482 | 15276    | Com Serv - MSC | Preventative Maintenance - MSC | Chiller Drian                      | Chiller                            | IFK Ice Plant                         | Completed | Scott Hamilton              |       |  | 2019-02-18     |
| WO-2480 | 15265    | Com Serv - MSC | Preventative Maintenance - MSC | Filter Backwash                    | Pool Sand Filters #1               | Main Floor Pool Mechanical Room       | Completed | Scott Hamilton              |       |  | 2019-02-14     |
| WO-2477 | 15278    | Com Serv - MSC | Preventative Maintenance - MSC | 52 Rink Boiler Inspection          | 52 Rink Boiler                     | 52 Lobby Furnace Room                 | Completed | Scott Hamilton              |       | Scott mentioned boiler external pipes need to clean. Worker has to run the boiler manually., Scott Pryde cleaned lines and replaced old valves with new ball valves. | 2019-02-21     |
| WO-2367 | 15266    | Com Serv - MSC | Preventative Maintenance - MSC | Filter Backwash                    | Pool Sand Filters #2               | Main Floor Pool Mechanical Room       | Completed | Scott Hamilton              |       |  | 2019-02-14     |
| WO-2119 | 15286    | Com Serv - MSC | Preventative Maintenance - MSC | Chiller Drian                      | 52 Chiller                         | 52 Ice Plant                          | Completed | Scott Hamilton              |       | drained two pails.   | 2019-02-19     |
| WO-2104 | 15243    | Com Serv - MSC | Preventative Maintenance - MSC |                                    | Pool Dressing Room Air Exchange    | Second Floor Pool Mechanical Room     | Completed | Dan Scott                   |       | Scott and Jason replaced the filter, Scott did the core wash.  | 2019-02-06     |
| WO-1878 | 15248    | Com Serv - MSC | Preventative Maintenance - MSC | Dehumidifier Belt and Filter Check | IFK Arena Dehumidifier East        | IFK Arena                             | Completed | Crystal Tan,<br>Jason Kabel |       | Crystal and Jason replaced the filters.  | 2019-02-05     |
| WO-1785 | 15290    | Com Serv - MSC | Preventative Maintenance - MSC | Dehumidifier Belt and Filter Check | Canadian Arena South Dehumidifier  | Canadian Arena                        | Completed | Scott Hamilton              |       |  | 2019-02-21     |
| WO-1784 | 15289    | Com Serv - MSC | Preventative Maintenance - MSC | Dehumidifier Belt and Filter Check | Canadian Arena North Dehumidifier  | Canadian Arena                        | Completed | Scott Hamilton              |       |  | 2019-02-21     |
| WO-1688 | 15245    | Com Serv - MSC | Preventative Maintenance - MSC | Filter/ Belt Inspection            | F-4-IFK East Dressing Room Furnace | IFK Second Floor Mechanical Room East | Completed | Scott Hamilton              |       | Crystal and Jason inspected it. Filters still good., Tyson said have to replace filtes., filters have been changed using 2-16x25x2 and 2-20x16x2 filters.            | 2019-02-21     |
| WO-1622 | 15253    | Com Serv - MSC | Preventative Maintenance -     | Filter/ Belt Inspection            | F-2 IFK Lobby HVAC                 | IFK Second Floor West Mechanical      | Completed | Crystal Tan,                |       | Crystal and Jason replaced the filters.  | 2019-02-04     |

| ID      | Asset ID | Department     | Work Order Type                | Work Order Subtype                 | Asset Name                  | Asset Location | Status    | Assigned To                 | Hours | All Notes                          | Completed Date |
|---------|----------|----------------|--------------------------------|------------------------------------|-----------------------------|----------------|-----------|-----------------------------|-------|------------------------------------|----------------|
|         |          |                | MSC                            |                                    |                             | Room           |           | Jason Kabel                 |       |                                    |                |
| WO-1587 | 15247    | Com Serv - MSC | Preventative Maintenance - MSC | Dehumidifier Belt and Filter Check | IFK Arena Dehumidifier West | IFK Arena      | Completed | Crystal Tan,<br>Jason Kabel |       | Jason replaced Dehumidifier Filter | 2019-02-04     |