

**TOWN OF FORT FRANCES**  
**Operations and Facilities Division - Environmental Area - Operations Statistics**  
(January 2016)

**STAFFING:**

See Operations Statistics (January) 2016 prepared by M. Strachan, Superintendent of Transportation

**OVERTIME HOURS - Equivalent Straight Time Hours**

See Operations Statistics (January) 2016 prepared by M. Strachan, Superintendent of Transportation

**WATER DISTRIBUTION:**

Water Main Breaks:

- Number of water main breaks: Two (2)
  - In front of 1024 York Ave. N. and Crowe Ave. - 600 blk.

Hydrant Repairs:

- Number of hydrant repairs: None

Hydrant Replacements:

- Number of hydrant replacements: None

Hydrant Installations (NEW):

- Number of new hydrant installations: None

Main Valve Repairs:

- Number of water main valve repairs: None

Water Service Breaks:

- Number of water service breaks: None

Water Service Repairs:

- Number of water service repairs: One (1)
  - 934 Kaitlyn Dr.

Main Valve Replacements:

- Number of main valve replacements: None

Water Service Turn "Off/On":

- Number of water service turn "Off/On": Six (6)
  - 418 Scott St., 700 Fifth St. W., 1027 Williams Ave., 713 Third St. W., 650 Fifth St. W. and 1144 Second St. E.

Frozen Water Services:

- Number of frozen water services: Three (3)
  - 229 Scott St., 800 Fifth St. W. and 650 Fifth St. W. (All froze within Owner's property)

Water Meter Installations/Replacements:

- Number of water meter installations/replacements: Three (3)
- 418 Scott St., 700 Fifth St. W. and 650 Fifth St. W.

Backflow Preventer Installations/Replacements:

- Number of backflow preventer installations/replacements: Three (3)
- 418 Scott St., 700 Fifth St. W. and 650 Fifth St. W.

Backflow Prevention - Testing:

- Number of backflow preventers tested: Three (3)
- 418 Scott St., 700 Fifth St. W. and 650 Fifth St. W.

Other Information:

- Replaced damaged fire hydrant markers

**WATER TREATMENT PLANT:**

- January 2016 - In receipt of the Water Treatment Plant Monthly Report.
- G. Wiedenhoft at plant to assist with maintenance and obtain some training.

**SEWERAGE COLLECTION:**

Wastewater Main Backups:

- Number of wastewater main backup: None

Sewer Main Repairs:

- Number of sewer main repairs: None

Sewer Service Breaks:

- Number of sewer service repairs: None

Sewer Service Repairs:

- Number of sewer service repairs: One (1)
- 505 McIrvine Rd.

Other Information:

- Summarized final costs for invoicing of private works associated with private works
- Cleaned Fifteen (15) plugged sewer services at the following locations:
  - 613 Third St. W., 428 Armit Ave. (2), 626 Third St. W., 155 Sixth St. W., 1026 Williams Ave., 1200 Scott St. (2), 556 Webster Ave., 1109 King's Hwy., 810 Third St. E., 375 Daniel Ave., 804 Wright Ave., 719 King's Hwy. and 246 Third St. W.
- January 20, 2016 - 229 Scott St. (Causeway Insurance) - Thawed the sanitary sewer service line using the low pressure steamer.
- Televised for Owner their sanitary sewer service - 218 Second St. E., 230 Third St. W. and 650 Fifth St. W.

**WASTE-WATER TREATMENT FACILITY:**

- January, 2016 - Received the Wastewater Treatment Facility Monthly Report.
- January 26 & 27, 2016 - Ministry of the Environment inspection.

## WASTE MANAGEMENT:

### Garbage Collection:

- Number of complaints regarding garbage collection:
  - Town - 0 complaints, Asselin's - 1 complaint

### Sanitary Landfill (Waste Disposal Site):

Landfill Scales functioning properly during this period.

- Amount of residential waste delivered to the landfill:
  - 127,940 kgs (127.94 tonnes)
- Amount of ICI waste delivered to the landfill:
  - 232,740 kgs (232.4 tonnes)

### Recycling:

- Number of complaints regarding recycled materials:
  - Town - 0 complaints, Asselin's - 0 complaints
- Amount of recycled waste diverted from the landfill:
  - Emterra - No data

Prepared By: \_\_\_\_\_

*[Signature]*

Environmental & Facilities Superintendent

Date: \_\_\_\_\_

*14-04-2016*