

Operations and Facilities Division - Environmental Area - Operations Statistics (February 2016)

STAFFING:

See Operations Statistics (February) 2016 prepared by M. Strachan, Superintendent of Transportation

OVERTIME HOURS - Equivalent Straight Time Hours

See Operations Statistics (February) 2016 prepared by M. Strachan, Superintendent of Transportation

WATER DISTRIBUTION:

Water Main Breaks:

- Number of water main breaks: One (1)
- Nelson St. (400 blk.)

Hydrant Repairs:

- Number of hydrant repairs: One (1)
- Sixth St. W. at Cornwall Ave. N.

Hydrant Replacements:

- Number of hydrant replacements: None

Hydrant Installations (NEW):

- Number of new hydrant installations: None

Main Valve Repairs:

- Number of water main valve repairs: None

Water Service Breaks:

- Number of water service breaks: None

Water Service Repairs:

- Number of water service breaks: None

Water Service Turn "Off/On":

- Number of water service turn "Off/On": Three (3)
- 1017 Second St. E., 1110 Second St. E. and 750 Thompson St.

Frozen Water Services:

- Number of frozen water services: Two (2) - Private Property
- 808 Wright Ave. and 650 Fifth St. W.

Water Meter Installations/Replacements:

- Number of water meter installations/replacements: None

Backflow Preventer Installations/Replacements:

- Number of backflow preventer installations/replacements: None

Backflow Prevention - Testing:

- Number of backflow preventers tested: None

Other Information:

- Summarized final costs for invoicing, associated with private works
- February 19 & 26, 2016 - J. Bruyere attended a First Aid Training course (2-day) at the Memorial Sports Centre
- February 22 - 26, 2016 - T. George attended a Water Distribution course (Class 2) in Dryden, Ontario - Keewaytinook Centre.

WATER TREATMENT PLANT:

- February 2016 - In receipt of the Water Treatment Plant Monthly Report.

SEWERAGE COLLECTION:

Wastewater Main Backups:

- Number of wastewater main backup: None

Wastewater Manhole Repairs:

- Number of wastewater manhole repairs: One (1)
 - Second St. E. at Armit Ave.

Sewer Service Repairs:

- Number of sewer service repairs: None

Other Information:

- Cleaned sixteen (16) plugged sewer services at the following locations:
 - 1234 Colonization Rd. W., 625 First St. E., 1332 Sixth St. E., 408 Third St. E., 637 Second St. E. (2),
 - 650 Fifth St. W., 315 Butler Ave., 1019 Second St. E., 1375 Colonization Rd. W., 822 Second St. E.
 - 1210 Scott St., 654 Thompson St., 1010 Walker Ave., 569 Scott St. and 726 Nelson St.

Private Works:

- CCTV inspected and traced various building sewer services.
- February 23, 2016 - 1010 Walker Ave. - CCTV'd the sewer service from cleanout inside house towards the main
- February 25, 2016 - 569 Scott St.. - traced the sewer service for Union Gas - clearance for cross-bore
- Performed locates for other utilities.

WASTE-WATER TREATMENT FACILITY:

- In receipt of the Wastewater Treatment Facility Monthly Report for February 2016.

WASTE MANAGEMENT:

Garbage Collection:

- Number of complaints regarding garbage collection:
 - Town - 0 complaints, Asselin's - 3 complaints

Sanitary Landfill (Waste Disposal Site):

Landfill Scales functioning properly during this period.

- Amount of residential waste delivered to the landfill:
 - 117,310 kgs (117.31 tonnes)
- Amount of ICI waste delivered to the landfill:
 - 189,930 kgs (189.93 tonnes)

Recycling:

- Number of complaints regarding recycled materials:
 - Town - 0 complaints, Asselin's - 1 complaint
- Amount of recycled waste diverted from the landfill:
 - Emterra - No data

Prepared By: _____

Environmental & Facilities Superintendent

Date: _____