

Workorder Summary Report

Report Start Date: Nov 1, 2021 12:00 AM  
Report End Date: Nov 30, 2021 11:59 PM  
Location: 1103\*  
Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM  
Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
<a href="#">2526040</a>			1103, Fort Frances WPCP	OPER	Inspection	1	MONTHS	Snow Removal at Wastewater Treatment (1m) 1103	COMP	11/1/21 12:00 AM	12/3/21 02:13 PM	12/3/21 02:13 PM	
<a href="#">2536270</a>	0000227376	PANEL ALARM/ DIALER	1103, Fort Frances WPCP, Process, Process Control & Monitoring	PM	Inspection	1	MONTHS	Critical Alarm/Dialer Testing (1m) 1103	COMP	11/1/21 12:00 AM	11/25/21 11:00 AM	11/25/21 12:00 PM	Dialer Test -We test everyday at 11am.
<a href="#">2536274</a>			1103, Fort Frances WPCP	PM	Refurbish/ Replace/Repair	1	MONTHS	Diesel Gensets Inspection/ Functional Tests (1m) 1103	COMP	11/1/21 12:00 AM	11/23/21 09:00 AM	11/23/21 10:00 AM	Monthly Gensets -All gensets were serviced and ran in November by Peterbuilt
<a href="#">2536290</a>			1103, Fort Frances WPCP	PM	Health and Safety	1	MONTHS	Health And Safety Inspection (1m) 1103	COMP	11/1/21 12:00 AM	11/25/21 07:00 AM	11/25/21 08:00 AM	Monthly H&S -Plow truck due to extensive rust.
<a href="#">2536615</a>			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	Blowers/Motors Inspection/Service (1m/3m) 1103	COMP	11/1/21 12:00 AM	11/23/21 07:45 AM	11/23/21 08:45 AM	Blower Maint. -I changed oil and greased Blower#4.
<a href="#">2536623</a>	0000246402	CENTRIFUGE GS2-2-1 TEACUP/ GRIT SNAIL	1103, Fort Frances WPCP, Process, Primary Treatment, Primary Sludge Degritting	PM	Inspection	1	MONTHS	Teacup Centrifuge Inspection/ Service (1m/3m/1y) 1103	COMP	11/1/21 12:00 AM	11/28/21 03:36 PM	11/28/21 03:36 PM	Teacup Centrifuge Inspection/ Service (1m/3m/1y) 1103 -Drained and inspected Teacup. Drained and hosed Snail, lubricated bearings and drive chain. KC
<a href="#">2537051</a>			1103, Fort Frances WPCP	PM	Refurbish/ Replace/Repair	1	YEARS	Tank Inspections (1y) 1103	COMP	11/1/21 12:00 AM	11/27/21 09:34 AM	11/27/21 09:34 AM	Tank Inspections (1y) 1103 -The tanks are in fine shape. KC
<a href="#">2542724</a>	0000246428	PUMP CENT BOUNDARY P1	1103, Boundary Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		Boundary P1 Pump Fail 1103	COMP		11/20/21 01:47 PM	11/20/21 01:53 PM	Boundary P1 Pump Fail -I went to the lift station and greased and backflushed P1 then I reset the alarm and monitored 3 pump cycles and they were normal.
<a href="#">2542725</a>	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		Whitepine Pump Fail 1103	COMP		11/20/21 01:55 PM	11/20/21 01:59 PM	Whitepine P1 Pump Fail -I went to the lift station and reset the alarm and backflushed the pump and watched 3 pump cycles and it acted normal.
<a href="#">2543078</a>	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		White Pine P1 Failure Alarm 1103	COMP		11/23/21 07:24 AM	11/23/21 07:31 AM	White Pine P1 Failure Alarm -I arrived at the lift station and reset the pump and unairlocked it. Then I monitored two pump cycles and it was normal.

Workorder Summary Report

Report Start Date: Nov 1, 2021 12:00 AM

Report End Date: Nov 30, 2021 11:59 PM

Location: 1103\*

Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM

Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
<a href="#">2543583</a>	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		White Pine P1 Fail 1103	COMP		11/26/21 08:53 AM	11/26/21 09:00 AM	White Pine P1 Fail -I arrived at the lift station and reset the pump then I opened the drywell to listen for anything out of sorts and it operated like normal. I then returned to the plant and monitored multiple pump cycles and they were also normal.
<a href="#">2544114</a>	0000246428	PUMP CENT BOUNDARY P1	1103, Boundary Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		Boundary Road Pump 1 fault call in 1103	COMP		11/30/21 02:00 AM	11/30/21 03:30 AM	Boundary Road Pump 1 fault call in 1103 -I was called by the auto dialler for a Pump 1 fault at Boundary Road lift station at 02200 hours. I opened a working alone ticket and drove to the station where I was able to reset the fault. The pump was then able to cycle correctly. Back at the wastewater plant I cleared the alarm on the SCADA computer. KC