

TOWN OF FORT FRANCES
Operations and Facilities Division - Environmental Area - Operations Statistics
(May 2015)

STAFFING:

See Operations Statistics (May) 2015 prepared by M. Strachan, Superintendent of Transportation

OVERTIME HOURS - Equivalent Straight Time Hours

See Operations Statistics (May) 2015 prepared by M. Strachan, Superintendent of Transportation

WATER DISTRIBUTION:

Water Main Breaks:

- Number of water main breaks: Three (3)
- Webster Ave. (500 blk.), Nelson St. (500 blk.) and in front of 213 Sixth St. W.

Hydrant Repairs:

- Number of hydrant repairs: None

Hydrant Replacements:

- Number of hydrant replacements: Four (4)
- In front of 618 First St. W. (HYD129), in front of 654 Riverview Dr. (HYD146),
- in front of 1101 Front St. (HYD344) and York Ave. N. at Eighth St. W. (HYD068)

Hydrant Installations (NEW):

- Number of new hydrant installations: None

Main Valve Repairs:

- Number of water main valve repairs: None

Main Valve Replacements:

- Number of water main valve replacements: Six (6)
- Minnie Ave. at Front St. (VAL551), Frenette Ave. at Fifth St. (VAL440), Third St. E. at Williams Ave. (VAL523),
- Church St. at Mowat Ave. (VAL221 & VAL212) and First St. W. at Morrison Cresc. (VAL102)

Water Service Breaks:

- Number of water service breaks: Two (2)
- 515 Nelson St. and 1301 Calder Dr.

Water Service Repairs:

- Number of water service repairs: None

Water Service Installations (NEW):

- Number of water service installations: One (1)
- 103 Sixth St. E.

Water Service Terminations:

- Number of water service terminations: None

Water Service Turn "Off/On":

- Number of water service turn "Off/On": Twenty-two (22)
 - 700 McIrvine Rd., 800 Calder Dr. (2), 1301 Calder Dr., 1000 Calder Dr., Point Park (2), 401 King's Hwy.
 - 901 Second St. E., 1214 Third St. E., 1404 King's Hwy., 1103 King's Hwy. (2), 400 Central Ave.,
 - 418 Scott St., 1300 Fifth St. E. (2), 1319 Colonization Rd. W., 621 Church St., 729 Church St.
 - and 1557 Colonization Rd. W. (2)

Frozen Water Services:

- Number of frozen water services: One (1)
 - 400 Central Ave.

Water Meter Installations/Replacements:

- Number of water meter installations/replacements: None

Backflow Preventer Installations/Replacements:

- Number of backflow preventer new installations: None

Backflow Preventer Annual Testing:

- Number of backflow preventer tested: Two (2)
 - 206 Victoria Ave. and 325 Scott St.

Other Information:

- May 4 & 21, 2015 - Completed a connection inspection of the water services at 1050 Walker Ave. N. & 103 Sixth St. E.
- May 25, 2015 - Roto-Rooter commenced cleaning and televising of the sanitary sewer mains
- Summarized final costs for invoicing of private works associated with private works
- Recorded locations of curbs stops at various locations.
- Sunny Cove Camp - continued with the re-assembling of the equipment for water system.
- Traced water service lines at various locations.
- Commenced with the valve exercising program (Area 1) and hydrant valve exercising.

WATER TREATMENT PLANT:

- May, 2015 - In receipt of the Water Treatment Facility Monthly Report.
- MC Lough Electric on site working on the installation of the new generator

SEWERAGE COLLECTION:

Wastewater Main Backups:

- Number of wastewater main backup: None

Sewer Main Repairs:

- Number of sewer main repairs: Two (2)
 - Nelson St. - 800 blk. And Wright Ave. (500 blk.)

Sewer Manhole Repairs:

- Number of sewer manhole repairs: None

Sewer Service Repairs:

- Number of sewer service repairs: One (1)
 - 986 King's Hwy.

Sewer Service Replacements:

- Number of sewer service installations: One (1)
 - 390 McIrvine Rd.

Sewer Service Installations (NEW):

- Number of water service installations: One (1)
 - 103 Sixth St. E.

Sewer Service Terminations:

- Number of water service terminations: None

Other Information:

- Cleaned eight (8) plugged sewer services at the following locations:
 - 407 Sixth St. W., 713 Webster Ave., 546 Second St. W., 1060 Cornwall Ave. N., 401 King's Hwy.
 - 1002 Crowe Ave. and 808 McKenzie Ave. (2).
- May 4 & 21, 2015 - Completed a connection inspection of the sewer services at 1050 Walker Ave. N. & 103 Sixth St. E.
- Recorded locations of cleanouts at various locations.
- Sewer main flushing (Dead Ends)
- Traced sanitary sewer service lines at various locations.

WASTE-WATER TREATMENT FACILITY:

- May, 2015 - Received the Wastewater Treatment Facility Monthly Report.

WASTE MANAGEMENT:

Garbage Collection:

- Number of complaints regarding garbage collection:
 - Town - 0 complaints, Asselin's - 0 complaints

Sanitary Landfill (Waste Disposal Site):

Landfill Scales functioning properly during this period.

- Amount of residential waste delivered to the landfill:
 - 306,170 kgs (306.17 tonnes)
- Amount of ICI waste delivered to the landfill:
 - 466,650 kgs (466.65 tonnes)
- May 9, 2015 - Free tipping day at the landfill for yard waste only (206 vehicles)
- May 19, 2015 - K.J. Refrigeration on site to remove the refrigerants from the appliances.
- May 5, 6 & 29, 2015 - Hauled cover material to landfill - cover garbage.

Recycling:

- Number of complaints regarding recycled materials:
 - Town - 0 complaints, Asselin's - 1 complaint
- Amount of recycled waste diverted from the landfill:
 - 28,910 kgs (28.91 tonnes) Metro

Prepared By: _____

Environmental & Facilities Superintendent

Date: _____