

Workorder Summary Report

Report Start Date: Feb 1, 2020 12:00 AM

Report End Date: Feb 29, 2020 11:59 PM

Location: 1103\*

Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM

Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
<a href="#">1617120</a>	0000227376	PANEL ALARM/DIALER	1103, Fort Frances WPCP, Process, Process Control & Monitoring	PM	Inspection	1	MONTHS	Critical Alarm/Dialer Testing (1m) 1103	COMP	2/1/20 12:00 AM	2/25/20 01:00 PM	2/25/20 01:00 PM	Monthly Dialer -We test daily .
<a href="#">1617124</a>			1103, Fort Frances WPCP	PM	Refurbish/Replace/Repair	1	MONTHS	Diesel Gensets Inspection/Functional Tests (1m) 1103	COMP	2/1/20 12:00 AM	2/23/20 01:00 PM	2/23/20 03:00 PM	Monthly Gensets -All gensets ran for one hour.
<a href="#">1617140</a>			1103, Fort Frances WPCP	PM	Health and Safety	1	MONTHS	Health And Safety Inspection (1m) 1103	COMP	2/1/20 12:00 AM	2/25/20 08:00 AM	2/25/20 09:00 AM	H&S Report -No issues at this point
<a href="#">1617151</a>			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	TPM Inspection/Maintenance (1m) 1103	COMP	2/1/20 12:00 AM	3/1/20 02:42 PM	3/1/20 02:42 PM	
<a href="#">1617479</a>			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	Blowers/Motors Inspection/Service (1m/3m) 1103	COMP	2/1/20 12:00 AM	2/25/20 09:00 AM	2/25/20 10:00 AM	Blower Maint -I greased all blowers.
<a href="#">1617487</a>	0000246402	CENTRIFUGE GS2-2-1 TEACUP/GRIT SNAIL	1103, Fort Frances WPCP, Process, Primary Treatment, Primary Sludge Degritting	PM	Inspection	1	MONTHS	Teacup Centrifuge Inspection/Service (1m/3m/1y) 1103	COMP	2/1/20 12:00 AM	2/25/20 11:00 AM	2/25/20 12:00 PM	Teacup Maint -I inspected and hosed the unit
<a href="#">1623475</a>	0000227421	PUMP CENT VERTICAL NON CLOG SEWAGE P1 FIFTH ST	1103, 5th St. Pumping Station, Process	CALL	Refurbish/Replace/Repair	0		Fifth St. Pump Fail 1103	COMP		2/16/20 03:25 PM	2/16/20 03:31 PM	Fifth St P1 Fail -I arrived at the lift station and reset the alarm, I then watched two pump cycles to be normal . I then returned to the plant and reset the alarm and watched another two pump cycles and it acted normal.
<a href="#">1624596</a>	0000246414	TANK PROCESS CLARIFIER SECONDARY CELL #1	1103, Fort Frances WPCP, Process, Secondary Treatment	CALL	Refurbish/Replace/Repair	0		Collector Failure 1103	COMP		2/25/20 08:29 AM	2/25/20 08:35 AM	Clarifer Long Collector 1 Failure -I arrived onsite and locked out the drive motor then changed the shear pin then restarted the drive motor. I then monitored for 30 minutes with no failures.