



TOWN OF FORT FRANCES
Operations and Facilities Division - Environmental Area - Operations Statistics
(November 2013)

STAFFING:

See Operations Statistics (November) 2013 prepared by M. Strachan, Superintendent of Transportation

OVERTIME HOURS - Equivalent Straight Time Hours

See Operations Statistics (November) 2013 prepared by M. Strachan, Superintendent of Transportation

WATER DISTRIBUTION:

Water Main Breaks:

- Number of water main breaks: None

Hydrant Repairs:

- Number of hydrant repairs: None

Hydrant Replacements:

- Number of hydrant replacements: None

Hydrant Installations (NEW):

- Number of new hydrant installations: None

Main Valve Repairs:

- Number of water main valve repairs: None

Water Service Breaks:

- Number of water service breaks: None

Water Service Repairs:

- Number of water service repairs: One (1)
- 400 Central Ave.

Water Service Installations (NEW):

- Number of water service installations: None

Water Service Replacements:

- Number of water service replacements: None

Water Service Terminations:

- Number of water service terminations: None

Water Service Turn "Off/On":

- Number of water service turn "Off/On": Twenty-eight (28)
 - 1702 Colonization Rd. W. (3), 111 Fourth St. W. (3), 1022 Williams Ave., 1242 Colonization Rd. W.,
 - 8 Armstrong Pl., 1207 Strachan Pl., 331 Second St. E., 1035 Cornwall Ave. N. (2), 609 Scott St.,
 - 1505 Colonization Rd. W., 400 Central Ave., 333 Church St. (4), 1404 King's Hwy., 297 Scott St.,
 - 928 Frenette Ave., 912 Sixth St. E., 646 First St. W., 951 McIrvine Rd. N. & 756 First St. W. (2)

Frozen Water Services:

- Number of frozen water services: None

Water Meter Installations/Replacements:

- Number of water meter installations/replacements: One (1)
 - 675 Flinder's Ave.

Backflow Preventer Installations/Replacements:

- Number of backflow preventer installations/replacements: One (1)
 - 675 Flinder's Ave.

Backflow Preventer Annual Testing:

- Number of backflow preventer tested: Two (2)
 - 675 Flinder's Ave. and 200 McIrvine Rd.

Other Information:

- Summarized final costs for invoicing of private works associated with private works
- Completed the hydrant flushing/winterizing program.
- Winterizing of the fire hydrants (Private Work).
- Recorded locations of curb stops at various locations.
- Completed with the valve turning program (Area 3) and hydrant valve exercising.
- November 6, 2013 - KLM Engineering in town to complete an inspection the water tower (3-year inspection)
- November 7, 2013 - Traced water service at 340 Church St. (Private Work)

WATER TREATMENT PLANT:

- November, 2013 - In receipt of the Water Treatment Plant Monthly Report
- November 15, 2013 - Workplace inspection done at the Water Treatment Plant and Water Tower.
- November 26, 2013 - Rod Seabrook, SAI GLOBAL completed an 12 month surveillance audit (off site) of the water system. A part of the accreditation process.

SEWERAGE COLLECTION:

Wastewater Main Backups:

- Number of wastewater main backup: None

Wastewater Main Repairs:

- Number of wastewater main repairs: None

Sewer Manhole Repairs:

- Number of sewer manhole repairs: None

Sewer Service Repairs:

- Number of sewer service repairs: One (1)
- 1035 Cornwall Ave. N.

Sewer Service Installations (NEW):

- Number of sewer service installations: None

Sewer Service Terminations:

- Number of sewer service terminations: None

Sewer Service Replacements:

- Number of sewer service installations: None

Other Information:

- Cleaned Seventeen (17) plugged sewer services at the following locations:
 - 108 Fifth St. W., 1045 River Rd. W., 700 Stewart St., 424 First St. E., 827 Armit Ave., 834 Portage Ave.,
 - 913 McKenzie Ave. N., 514 Central Ave., 905 Kaitlyn Dr., 232 Second St. E., 529 First St. E.,
 - 201 Sixth St. W., 601 Second St. W., 1029 Portage Ave. N., 708 Portage Ave., 1035 Portage Ave. N.
 - and 648 Second St. E.
- Sewer main flushing (Dead Ends and Trouble Areas) - Area 3
- CCTV inspected various building sewer services.
- Recorded locations of cleanouts at various locations.
- Sewer service connection inspections at 1035 Cornwall Ave. N. & 1029 Portage Ave. N.

WASTE-WATER TREATMENT FACILITY:

- November, 2013 - In receipt of the Wastewater Treatment Facility Monthly Report.

WASTE MANAGEMENT:

Garbage Collection:

- Number of complaints regarding garbage collection:
 - Town - 0 complaints, Asselin's - 0 complaints

Sanitary Landfill (Waste Disposal Site):

Landfill Scales functioning good during this period.

- Amount of residential waste delivered to the landfill:
 - 203,070 kgs (203.07 tonnes)
- Amount of ICI waste delivered to the landfill:
 - 324,330 kgs (324.33 tonnes)
- Trillum from Thunder Bay removed more tires from the landfill site.

Recycling:

- Number of complaints regarding recycled materials:
 - Town - 0 complaints, Asselin's - 2 complaints
- Amount of recycled waste diverted from the landfill:
 - 30,820 kgs (30.82 tonnes) Metro

Prepared By: _____

Environmental & Facilities Superintendent

Date: _____