

Workorder Summary Report

Report Start Date: Dec 1, 2021 12:00 AM
Report End Date: Dec 31, 2021 11:59 PM
Location: 1103*
Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM
Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
2576626	0000227376	PANEL ALARM/ DIALER	1103, Fort Frances WPCP, Process, Process Control & Monitoring	PM	Inspection	1	MONTHS	Critical Alarm/Dialer Testing (1m) 1103	COMP	12/1/21 12:00 AM	12/22/21 11:00 AM	12/22/21 12:00 PM	Dialer Test -We test daily at 11.
2576630			1103, Fort Frances WPCP	PM	Refurbish/ Replace/Repair	1	MONTHS	Diesel Gensets Inspection/ Functional Tests (1m) 1103	COMP	12/1/21 12:00 AM	12/23/21 08:00 AM	12/23/21 10:00 AM	Monthly Gensets -I ran all lift stations under load 1 hour.
2576646			1103, Fort Frances WPCP	PM	Health and Safety	1	MONTHS	Health And Safety Inspection (1m) 1103	COMP	12/1/21 12:00 AM	12/23/21 06:00 AM	12/23/21 07:00 AM	H&S Inspection -Plow truck box is rusty and should not be used or entered.
2576979			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	Blowers/Motors Inspection/Service (1m/3m) 1103	COMP	12/1/21 12:00 AM	12/22/21 01:30 PM	12/22/21 02:30 PM	Blower Maint -I greased all blowers.
2576989	0000246402	CENTRIFUGE GS2-2-1 TEACUP/ GRIT SNAIL	1103, Fort Frances WPCP, Process, Primary Treatment, Primary Sludge Degritting	PM	Inspection	1	MONTHS	Teacup Centrifuge Inspection/ Service (1m/3m/1y) 1103	COMP	12/1/21 12:00 AM	12/22/21 10:30 AM	12/22/21 11:30 AM	Monthly Teacup -I removed the lid and found minimal debris then I returned it to service.
2579383	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		White Pine Pump Issues 1103	COMP		12/1/21 08:03 AM	12/1/21 08:08 AM	White Pine Pump Issues -I got called in to assist in a confined space entry .
2579832			Fort Frances Water Pollution Control Plant	CALL	Refurbish/ Replace/Repair	0		Longitudinal collector 2 failure call in 1103	COMP		12/3/21 01:35 AM	12/3/21 03:45 AM	Longitudinal collector 2 failure call in 1103 -I was called by the auto dialler at 0135 hours for a longitudinal collector 2 failure. I opened a working alone ticket and drove to the plant. When I arrived I acknowledged alarms on the SCADA computer. After replacing a broken shear pin and adjusting the tensioner arm, it started and ran nicely. Closed ticket 0345 hours

Workorder Summary Report

Report Start Date: Dec 1, 2021 12:00 AM

Report End Date: Dec 31, 2021 11:59 PM

Location: 1103*

Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM

Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
2580064	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		White Pine P1 Failure 1103	COMP		12/5/21 10:34 AM	12/5/21 10:42 AM	White Pine P1 Failure -I arrived at the lift station to find both pumps were airlocked. After unairlocking both pumps I waited for the level in the wetwell to get fairly high so that it would reset both floats then I returned both pumps to auto. I then returned to the plant where I monitored several pump cycles to be normal.
2580375	0000227360	MOTOR PUMP DIGESTER SLUDGE #1	1103, Fort Frances WPCP, Process, Sludge Treatment & Handling, Sludge Digestion	CALL	Refurbish/ Replace/Repair	0		Plant General alarm 1103	COMP		12/7/21 11:31 AM	12/7/21 11:37 AM	Digester Doghouse Temp Alarm -I arrived at work to find the digester building to be low in temp, So I plugged in an extension cord to the yard receptacles and plugged another heater in and placed it in the building. I then monitored the temp rise.
2581274	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		White Pine lift station pump 1 failure call in 1103	COMP		12/11/21 11:20 PM	12/12/21 12:35 AM	White Pine lift station pump 1 failure call in 1103 -I was called at 2320 hours Dec. 11/21 by the auto dialer for a White Pine lift station pump failure. I drove to the wastewater plant where I acknowledged the alarms on the SCADA computer, then proceeded to the lift station where I was able to reset the pump fault and observed proper pump cycling at 0030 hours Dec. 12/21

Workorder Summary Report

Report Start Date: Dec 1, 2021 12:00 AM
Report End Date: Dec 31, 2021 11:59 PM
Location: 1103*
Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM
Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
2582124	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		White Pine lift station pump 1 fault call in 1103	COMP		12/15/21 05:55 PM	12/15/21 09:45 PM	White Pine lift station pump 1 fault Dec 15/21 -I was called by the auto dialer at 1755 hours for a pump fault at White Pine lift station. I drove to the plant and acknowledged alarms on the SCADA computer and then proceeded to the lift station where I reset the pump fault. Unfortunately the pump faulted on the next pump cycle. I informed my manager that I would ask Dale Hughes for assistance to pull and clean the pump. The pump was pulled and then put back into service successfully 2100 hours.
2582130	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		White Pine P1 Fail 1103	COMP		12/16/21 08:05 AM	12/16/21 08:10 AM	White Pine P1 Fail -I was called in to assist in pulling and checking pump.
2582511	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		White Pine P1 Fail Alarm 1103	COMP		12/18/21 07:22 AM	12/18/21 07:27 AM	White Pine P1 Failure -I arrived at the lift station and reset the pump and it acted normal after the reset.I then returned to the plant to check trending and to monitor.
2582745	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		White Pine P1 Fail Alarm 1103	COMP		12/20/21 08:17 AM	12/20/21 08:22 AM	White Pine P1 Fail -I reset the pump at the lift station then returned to plant to monitor a few pump cycles. We are awaiting parts to repair issue.

Workorder Summary Report

Report Start Date: Dec 1, 2021 12:00 AM

Report End Date: Dec 31, 2021 11:59 PM

Location: 1103*

Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM

Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
2583513	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		White Pine lift station pump fault call in 1103	COMP		12/24/21 07:40 PM	12/24/21 09:15 PM	White Pine lift station pump fault call in Dec 24 - I was called by the auto dialer for a White Pine lift station pump fault at1940 hours Dec 24th. I drove to the plant where I acknowledged alarms on the SCADA computer and then proceeded to the lift station and was able to reset the fault. It is important to note that starter and overload for this motor are on order and will be installed at the earliest opportunity.
2583862	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		White Pine lift station pump fault call in Dec 28	COMP		12/28/21 09:00 PM	12/28/21 10:05 PM	White Pine lift station pump fault call in Dec 28 -I was called by the auto dialer for a White Pine lift station pump fault at 2100 hours December 28th . I drove to the station where I reset the fault and the pump then ran correctly. I went back to the wastewater plant where I reset SCADA computer alarms and verified that the pump was cycling.
2584159	0000227447	PUMP CENT #1 VERTICAL NON CLOG SEWAGE P1 WHITEPINE	1103, White Pine Pumping Station, Process	CALL	Refurbish/ Replace/Repair	0		December 31 White Pine liftstation pump fault call in 1103	COMP		12/31/21 03:19 AM	12/31/21 05:00 AM	December 31 White Pine liftstation pump fault call in 1103 -I was called by the auto dialer at 0319 hours for a White Pine lift station pump fault. I drove to the plant where I acknowledged alarms on the SCADA computer and proceeded to the lift station where I reset the pump fault. Back at the plant I monitored several pump cycles. There are starter and overload parts on order for this station.