

Workorder Summary Report

Report Start Date: Jan 1, 2021 12:00 AM

Report End Date: Jan 31, 2021 11:59 PM

Location: 1103*

Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM

Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
2072337			1103, Fort Frances WPCP	OPER	Inspection	1	MONTHS	Snow Removal at Wastewater Treatment (1m) 1103	COMP	1/1/21 12:00 AM	2/8/21 07:05 AM	2/8/21 07:05 AM	
2085516	0000227376	PANEL ALARM/DIALER	1103, Fort Frances WPCP, Process, Process Control & Monitoring	PM	Inspection	1	MONTHS	Critical Alarm/Dialer Testing (1m) 1103	COMP	1/1/21 12:00 AM	1/30/21 11:00 AM	1/30/21 12:00 PM	Dialer Test -We test daily
2085520			1103, Fort Frances WPCP	PM	Refurbish/Replace/Repair	1	MONTHS	Diesel Gensets Inspection/Functional Tests (1m) 1103	COMP	1/1/21 12:00 AM	1/25/21 07:07 AM	1/25/21 07:07 AM	Diesel Gensets Inspection/Functional Tests -January 24, 2021 exercised all generators
2085537			1103, Fort Frances WPCP	PM	Health and Safety	1	MONTHS	Health And Safety Inspection (1m) 1103	COMP	1/1/21 12:00 AM	1/30/21 07:30 AM	1/30/21 08:30 AM	H&S Report -No issues.
2085548			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	TPM Inspection/Maintenance (1m) 1103	COMP	1/1/21 12:00 AM	2/8/21 07:17 AM	2/8/21 07:17 AM	
2085553			1103, Fort Frances WPCP	OPER	Compliance	1	MONTHS	WISKI Review (1m) 1103	COMP	1/1/21 12:00 AM	2/8/21 07:16 AM	2/8/21 07:16 AM	
2085967			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	Blowers/Motors Inspection/Service (1m/3m) 1103	COMP	1/1/21 12:00 AM	1/19/21 11:30 AM	1/19/21 12:30 PM	Blower Maint. -I changed oil , greased and tightened belts on blower # 4 .
2085975	0000246402	CENTRIFUGE GS2-2-1 TEACUP/GRIT SNAIL	1103, Fort Frances WPCP, Process, Primary Treatment, Primary Sludge Degritting	PM	Inspection	1	MONTHS	Teacup Centrifuge Inspection/Service (1m/3m/1y) 1103	COMP	1/1/21 12:00 AM	1/27/21 01:08 PM	1/27/21 01:08 PM	Teacup Centrifuge Inspection/Service -Drained teacup and snail for inspection, no debris. Greased bearings and lubricated chain on snail.