

## **Operations and Facilities Division - Environmental Area - Operations Statistics (February 2018)**

### **STAFFING:**

See Operations Statistics (February) 2018 prepared by M. Strachan, Superintendent of Transportation

### **OVERTIME HOURS - Equivalent Straight Time Hours**

See Operations Statistics (February) 2018 prepared by M. Strachan, Superintendent of Transportation

### **WATER DISTRIBUTION:**

#### Water Main Breaks:

- Number of water main breaks: None

#### Hydrant Repairs:

- Number of hydrant repairs: None

#### Hydrant Replacements:

- Number of hydrant replacements: None

#### Hydrant Installations (NEW):

- Number of new hydrant installations: None

#### Main Valve Repairs:

- Number of water main valve repairs: None

#### Water Service Breaks:

- Number of water service breaks: None

#### Water Service Repairs:

- Number of water service breaks: None

#### Water Service Turn "Off/On":

- Number of water service turn "Off/On": Eight (8)
  - 545 Elm Ave., 809 Christie Ave., 820 Huffman Ct., 237 Church St. (3), 825 Cornwall Ave.
  - 920 Williams Ave.

#### Frozen Water Services:

- Number of frozen water services: Twenty-seven (27)
  - 1702 Colonization Rd. W., 1103 River Rd. W., 1617 Colonization Rd. W. (2), 833 Armit Ave. (2),
  - 143 Fourth St. W., 1123 Scott St., 127 Sixth St. E., 1004 Crowe Ave., 1012 Victoria Ave. N.,
  - 621 Scott St., 426 Third St. W., 909 Christie Ave. N. (2), 513 Armit Ave., 913 McKenzie Ave. N.,
  - 1227 Third St. E., 1337 Emo Rd., 237 Church St., 415 Third St. W., 1115 River Rd. W.,
  - 1032 Victoria Ave. N., 271 Scott St., 825 Crowe Ave., 1104 Victoria Ave. N.
  - and 1411 Colonization Rd. W.

#### Water Meter Installations/Replacements:

- Number of water meter installations/replacements: One (1)
  - 710 Fifth St. W.

#### Backflow Preventer Installations/Replacements:

- Number of backflow preventer installations/replacements: One (1)
- 710 Fifth St. W.

#### Backflow Prevention - Testing:

- Number of backflow preventers tested: One (1)
- 710 Fifth St. W.

#### Other Information:

- Summarized final costs for invoicing, associated with private works
- Delivered sixteen (16) delinquent account notices.
- February 12 & 13, 2018 - G. Wiedenhoeft and L. Carmody attended a Red Cross First Aid Training Standard First Aid & CPR Level 'C'. Held in the Memorial Sportsplex - Training Room, Fort Frances.
- February 15, 2018 - G. Wiedenhoeft, T. George, J. Bruyere and L. Carmody attended the mandatory water operator course "Safe Drinking Water Operators Essentials". Held in the Shaw Room, F.F. Library.
- Replaced damaged and faded hydrant markers.

#### **WATER TREATMENT PLANT:**

- February 2018 - In receipt of the Water Treatment Plant Monthly Report.
- February 15, 2018 - R. White and B. Webb attended the mandatory water operator course "Safe Drinking Water Operators Essentials". Held in the Shaw Room, F.F. Library.

#### **SEWERAGE COLLECTION:**

##### Wastewater Main Backups:

- Number of wastewater main backup: None

##### Wastewater Manhole Repairs:

- Number of wastewater manhole repairs: None

##### Sewer Service Repairs:

- Number of sewer service repairs: None

##### Other Information:

- Cleaned Twenty (20) plugged sewer services at the following locations:
  - 613 Second St. E., 1150 Walker Ave., 601 Second St. E., 340 Church St., 318 Second St. E.,
  - 1132 First St. E., 907 Fifth St. E., 514 Central Ave., 904 Third St. E., 819 Victoria Ave.,
  - 934 Victoria Ave. N., 316 Second St. E., 634 Riverview Dr., 532 Second St. W., 724 Nelson St.,
  - 239 Fifth St. E., 1123 First St. E., 1617 Colonization Rd. W., 521 Second St. W. and
  - 411 B Third St. E.

##### Private Works:

- CCTV inspected building sewer services at 1201 Idywild Dr., 924 Fifth St. E. and 808 Wright Ave.
- February 20, 2018 - 904 third St. E. - completed a connection inspection of the sanitary service.
- Performed locates for other utilities.

#### **WASTE-WATER TREATMENT FACILITY:**

- In receipt of the Wastewater Treatment Facility Monthly Report for February 2018.

## **WASTE MANAGEMENT:**

### Garbage Collection:

- Number of complaints regarding garbage collection:
  - Town - 0 complaints, Asselin's - 2 complaints

### Sanitary Landfill (Waste Disposal Site):

Landfill Scales functioning properly during this period.

- Amount of residential waste delivered to the landfill:
  - 125,000 kgs (125.00 tonnes)
- Amount of ICI waste delivered to the landfill:
  - 272,440 kgs (272.44 tonnes)

### Recycling:

- Number of complaints regarding recycled materials:
  - Town - 0 complaints, Asselin's - 1 complaint
- Amount of recycled waste diverted from the landfill:
  - Emterra - No data

Prepared By: \_\_\_\_\_

Environmental & Facilities Superintendent

Date: \_\_\_\_\_