

TOWN OF FORT FRANCES
Operations and Facilities Division - Environmental Area - Operations Statistics
(June 2015)

STAFFING:

See Operations Statistics (June) 2015 prepared by M. Strachan, Superintendent of Transportation

OVERTIME HOURS - Equivalent Straight Time Hours

See Operations Statistics (June) 2015 prepared by M. Strachan, Superintendent of Transportation

WATER DISTRIBUTION:

Water Main Breaks:

- Number of water main breaks: None

Hydrant Repairs:

- Number of hydrant repairs: None

Hydrant Replacements:

- Number of hydrant replacements: None

Hydrant Installations (NEW):

- Number of new hydrant installations: None

Main Valve Repairs:

- Number of water main valve repairs: One (1)
 - Lillie Ave. at King's Hwy. (VAL160)

Main Valve Replacements:

- Number of water main valve replacements: None

Water Service Breaks:

- Number of water service breaks: None

Water Service Repairs:

- Number of water service repairs: Five (5)
 - 413 Third St. E., 228 Sixth St. E., 600 Fifth St. W., 1209 Second St. E. and 930 Fifth St. W.

Water Service Installations (NEW):

- Number of water service installations: None

Water Service Replacements:

- Number of water service replacements: None

Water Service Terminations:

- Number of water service terminations: None

Water Service Turn "Off/On":

- Number of water service turn "Off/On": Eleven (11)
 - 413 Third St. E. (2), 901 Second St. E., 924 Fifth St. E. (2), 389 Daniel Ave. (3), 237 Fifth St. E.,
 - and 700 Armit Ave. (2)

Frozen Water Services:

- Number of frozen water services: None

Water Meter Installations/Replacements:

- Number of water meter installations/replacements: None

Backflow Preventer Installations/Replacements:

- Number of backflow preventer installations/replacements: None

Backflow Prevention - Testing:

- Number of backflow preventers tested: Five (5)
 - 1250 King's Hwy., 238 Church St., 858 Sixth St. W., 206 Scott St. and 237 Fifth St. E.

Other Information:

- Summarized final costs for invoicing of private works associated with private works
- Traced various building water services.
- Continued with the valve exercising program (Area 1) and hydrant valve exercising.
- Recorded locations of curb stops at various locations.
- June 3 & 4, 2015 - Assisted Couchiching F. N. in the repair of the 10" water main along Mill Rd.

WATER TREATMENT PLANT:

- June, 2015 - In receipt of the Water Treatment Facility Monthly Report.
- June 2, 2015 - Century Cranes on site to inspect the hoists and lifts.
- MC Lough Electric on site working on the installation of the new generator

SEWERAGE COLLECTION:

Wastewater Main Backups:

- Number of wastewater main backup: One (1)
 - King's Hwy. (900 blk.)

Wastewater Main Repairs:

- Number of wastewater main repairs: One (1)
 - Banta Blvd. (900 blk.)

Wastewater Manhole Repairs:

- Number of wastewater manhole repairs: One (1)
 - Fifth St. W. (800 blk.)

Sewer Service Repairs:

- Number of sewer service repairs: None

Sewer Service Replacements:

- Number of sewer service replacements: One (1)
 - McIrvine Rd. - 390

Sewer Service Installations (NEW):

- Number of sewer service installations: None

Sewer Service Terminations:

- Number of water service terminations: None

Other Information:

- Cleaned thirteen (13) plugged sewer services at the following locations:
 - 1024 Fifth St. E., 812 Cornwall Ave., 1000 First St. E., 401 King's Hwy., 610 First St. W., 810 Armit Ave.,
 - 902 Phair Ave., 806 Shevlin Ave., 626 Church St., 831 Armit Ave., 810 Crowe Ave., 831 King's Hwy.
 - and 702 Armit Ave.
- CCTV inspected and traced various building sewer services.
- Recorded locations of cleanouts at various locations.
- June 19, 2015 - Roto-Rooter completed the cleaning and televising the sanitary sewer mains

WASTE-WATER TREATMENT FACILITY:

- June 3 & 4, 2015 - Century Cranes in to complete the inspections of hoists and lifts.
- June 2015 - In receipt of the Wastewater Treatment Facility Monthly Report.

WASTE MANAGEMENT:

Garbage Collection:

- Number of complaints regarding garbage collection:
 - Town - 0 complaints, Asselin's - 2 complaints

Sanitary Landfill (Waste Disposal Site):

Landfill Scales functioning properly during this period.

- Amount of residential waste delivered to the landfill:
 - 291,380 kgs (291.38 tonnes)
- Amount of ICI waste delivered to the landfill:
 - 389,210 kgs (389.21 tonnes)
- June 9, 2015 - Hauled cover material to landfill - cover garbage.
- June 22, 2015 - Bay City hauled asphalt to the landfill off the highway to build a turn-around area for garbage disposal.

Recycling:

- Number of complaints regarding recycled materials:
 - Town - 0 complaints, Asselin's - 1 complaint
- Amount of recycled waste diverted from the landfill:
 - 50,570 kgs (50.57 tonnes) Cascade Recovery Inc.

Prepared By:

JLH

Environmental & Facilities Superintendent

Date:

04-10-2015