

TOWN OF FORT FRANCES
Operations and Facilities Division - Environmental Area - Operations Statistics
(August 2016)

STAFFING:

See Operations Statistics (August) 2016 prepared by M. Strachan, Superintendent of Transportation

OVERTIME HOURS - Equivalent Straight Time Hours

See Operations Statistics (August) 2016 prepared by M. Strachan, Superintendent of Transportation

WATER DISTRIBUTION:

Water Main Breaks:

- Number of water main breaks: One (1)
- In front of 338 Scott St.

Hydrant Repairs:

- Number of hydrant repairs: One (1)
- In front of 360 Scott St. (HYD337)

Hydrant Replacements:

- Number of hydrant replacements: None

Hydrant Installations (NEW):

- Number of new hydrant installations: None

Main Valve Repairs:

- Number of water main valve repairs: Seven (7)
 - Front St./Armit Ave. (VAL544), Fifth St. E. - 1200 Blk. (VAL514), Colon. Rd. W./Lyndy Pl. N. (VAL007),
 - Colon. Rd. W./Lyndy Pl. N. (VAL008), Colon. Rd. W./Kerr Pl. (VAL019), Emo Rd./Kirsti Pl. (VAL555)
 - and Third St. E. /Williams Ave. (VAL501)

Water Service Breaks:

- Number of water service breaks: One (1)
- In front of 515 First St. E.

Water Service Repairs:

- Number of water service repairs: None

Water Service Installations (NEW):

- Number of water service installations: None

Water Service Replacements:

- Number of water service replacements: None

Water Service Terminations:

- Number of water service terminations: None

Water Service Turn "Off/On":

- Number of water service turn "Off/On": Eleven (11)
- 906 Second St. E. (2), 1119 King's Hwy. (2), 1232 King's Hwy. (2), 459 Church St. (2), 1228 Third St. E.,
- 500 Church St. and 228 Third St. E.

Frozen Water Services:

- Number of frozen water services: None

Water Meter Installations/Replacements:

- Number of water meter installations/replacements: None

Backflow Preventer Installations/Replacements:

- Number of backflow preventer installations/replacements: None

Backflow Prevention - Testing:

- Number of backflow preventers tested: Seven (7)
- 500 King's Hwy., 1000 McIrvine Rd., 404 Scott St., 601 Mowat Ave., 279 Scott St., 401 King's Hwy.
- and 862 King's Hwy.

Other Information:

- Summarized final costs for invoicing associated with private works
- Recorded locations of curb stops at various locations.
- Continued with locates (as required) of the Town's infrastructure for various Contractors/Utility Companies.
- Continued with the valve exercising program (Area 5)
- Worked in conjunction with Makkinga Contracting and Bay City Contracting disinfecting and water quality testing before putting the new water main, service lines and hydrants into service.

WATER TREATMENT PLANT:

- August, 2016 - In receipt of the Water Treatment Plant Monthly Report

SEWERAGE COLLECTION:

Wastewater Main Backups:

- Number of wastewater main backup: None

Wastewater Main Repairs:

- Number of wastewater main repairs: None

Wastewater Manhole Repairs:

- Number of wastewater manhole repairs: None

Sewer Service Breaks:

- Number of sewer service breaks: None

Sewer Service Repairs:

- Number of sewer service repairs: None

Sewer Service Installations (NEW):

- Number of sewer service installations: None

Sewer Service Terminations:

- Number of sewer service terminations: None

Sewer Service Replacements:

- Number of sewer service replacement: None

Other Information:

- Cleaned Eight (8) plugged sewer services at the following locations:
 - 306 Third St. E. (2), 508 Church St., 922 Third St. E., 316 Second St. E., 200 Sixth St. E.,
 - 432 Second St. E. and 1110 Nelson St.
- August 22, 2016 - Assisted Rainy River in the cleaning of their sanitary sewer mains.
- August 23, 2016 - Flushed/cleaned sewer main at 1305 Mill Rd. (Lakeview Trailer Park).
- August 23, 2016 - Flushed/cleaned sewer main on Nelson St. (1100 blk.) and Stewart St. (700 blk.)
- CCTV inspected various building sewer services.
- Recorded locations of cleanouts at various locations.

WASTE-WATER TREATMENT FACILITY:

- August, 2016 - In receipt of the Wastewater Treatment Facility Monthly Report.

WASTE MANAGEMENT:

Garbage Collection:

- Number of complaints regarding garbage collection:
 - Town - 0 complaints, Asselin's - 3 complaints

Sanitary Landfill (Waste Disposal Site):

Landfill Scales functioning properly during this period.

- Amount of residential waste delivered to the landfill:
 - 247,720 kgs (247.72 tonnes)
- Amount of ICI waste delivered to the landfill:
 - 583,220 kgs (583.22 tonnes)

Recycling:

- Number of complaints regarding recycled materials:
 - Town - 0 complaints, Asselin's - 0 complaints
- Amount of recycled waste diverted from the landfill:
 - No Data - Emterra Environmental

Prepared By: _____

Environmental & Facilities Superintendent

Date: _____