

Workorder Summary Report

Report Start Date: Mar 1, 2022 12:00 AM
Report End Date: Mar 31, 2022 11:59 PM
Location: 1103*
Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM
Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
2721816	0000246376	GEAR DRIVE SC 4-2-1	1103, Fort Frances WPCP, Process	CALL	Refurbish/ Replace/Repair	0		Longitudinal collector 2 failure call in 1103	COMP		3/5/22 05:30 PM	3/5/22 07:15 PM	Longitudinal collector 2 failure call in 1103 - I was called by the auto dialer for a collector failure alarm at 1730 hours. When I arrived at the plant, I acknowledged the longitudinal collector number 2 alarms on SCADA. A shear pin was broken and once replaced the clarifier collector was in operation again (1830 hours).
2723868	0000246376	GEAR DRIVE SC 4-2-1	1103, Fort Frances WPCP, Process	CALL	Refurbish/ Replace/Repair	0		Mar 14 Longitudinal collector 2 failure call in 1103	COMP		3/14/22 05:45 PM	3/14/22 07:15 PM	Mar 14 Longitudinal collector 2 failure call in 1103 - I was called by the auto dialer for a collector failure at 1745 hours. I drove to the plant where I acknowledged alarms on the SCADA computer and proceeded to replace a broken shear pin on longitudinal collector 2 gear drive. A restart of the collector was then possible without any more trouble.
2705002			1103, Fort Frances WPCP	OPER	Inspection	1	MONTHS	Snow Removal at Wastewater Treatment (1m) 1103	COMP	3/1/22 12:00 AM	4/3/22 02:56 PM	4/3/22 02:56 PM	
2717975	0000227376	PANEL ALARM/ DIALER	1103, Fort Frances WPCP, Process, Process Control & Monitoring	PM	Inspection	1	MONTHS	Critical Alarm/Dialer Testing (1m) 1103	COMP	3/1/22 12:00 AM	3/27/22 11:00 AM	3/27/22 12:00 PM	Dialer Test - We test daily.
2717979			1103, Fort Frances WPCP	PM	Refurbish/ Replace/Repair	1	MONTHS	Diesel Gensets Inspection/ Functional Tests (1m) 1103	COMP	3/1/22 12:00 AM	3/31/22 02:27 PM	3/31/22 02:27 PM	Diesel Gensets Inspection/ Functional Tests (1m) 1103 - Ran gensets at lift stations as well as the portable Yamaha. Peterbilt replaced a fuel line on Fifth Street genset
2717995			1103, Fort Frances WPCP	PM	Health and Safety	1	MONTHS	Health And Safety Inspection (1m) 1103	COMP	3/1/22 12:00 AM	3/27/22 07:00 AM	3/27/22 08:00 AM	H&S Inspection - Plow truck box still unsafe to use. due to rust
2718006			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	TPM Inspection/Maintenance (1m) 1103	COMP	3/1/22 12:00 AM	4/3/22 02:56 PM	4/3/22 02:56 PM	
2718351			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	Blowers/Motors Inspection/Service (1m/3m) 1103	COMP	3/1/22 12:00 AM	3/28/22 02:00 PM	3/28/22 03:00 PM	Blower Maint. - I greased all blowers.

Workorder Summary Report

Report Start Date: Mar 1, 2022 12:00 AM

Report End Date: Mar 31, 2022 11:59 PM

Location: 1103*

Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM

Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
2718361	0000246402	CENTRIFUGE GS2-2-1 TEACUP/ GRIT SNAIL	1103, Fort Frances WPCP, Process, Primary Treatment, Primary Sludge Degritting	PM	Inspection	1	MONTHS	Teacup Centrifuge Inspection/ Service (1m/3m/1y) 1103	COMP	3/1/22 12:00 AM	3/31/22 02:50 PM	3/31/22 02:50 PM	Teacup Centrifuge Inspection/ Service (1m/3m/1y) 1103 - Drained and inspected Teacup and found no debris. Greased bearings and lubricated drive chain
2715204	0000246402	CENTRIFUGE GS2-2-1 TEACUP/ GRIT SNAIL	1103, Fort Frances WPCP, Process, Primary Treatment, Primary Sludge Degritting	CALL	Refurbish/ Replace/Repair	0		Screen Inlet High Level 1103	COMP		3/1/22 08:03 AM	3/1/22 08:13 AM	Screen Inlet High Level Alarm - I arrived onsite to find the screen to not be running . I then turned the MCC breaker off and on and it restarted the screen. I then monitored a normal start and stop.