

TOWN OF FORT FRANCES
Operations and Facilities Division - Environmental Area - Operations Statistics
(July 2016)

STAFFING:

See Operations Statistics (July) 2016 prepared by M. Strachan, Superintendent of Transportation

OVERTIME HOURS - Equivalent Straight Time Hours

See Operations Statistics (July) 2016 prepared by M. Strachan, Superintendent of Transportation

WATER DISTRIBUTION:

Water Main Breaks:

- Number of water main breaks: None

Hydrant Repairs:

- Number of hydrant repairs: None

Hydrant Replacements:

- Number of hydrant replacements: None

Hydrant Installations (NEW):

- Number of new hydrant installations: None

Main Valve Repairs:

- Number of water main valve repairs: None

Main Valve Replacements:

- Number of water main valve replacements: None

Water Service Breaks:

- Number of water service breaks: One (1)
 - Point Park

Water Service Repairs:

- Number of water service repairs: Three (3)
 - 930 Third St. E., 906 Second St. E. and 238 Second St. E.

Water Service Installations (NEW):

- Number of water service installations: Five (5)
 - Nelson Street (600 blk.) - Town House (Five Services)

Water Service Replacements:

- Number of water service replacements: None

Water Service Terminations:

- Number of water service terminations: None

Water Service Turn "Off/On":

- Number of water service turn "Off/On": Two (2)
 - 862 King's Hwy. and 714 Victoria Ave.

Frozen Water Services:

- Number of frozen water services: None

Water Meter Installations/Replacements:

- Number of water meter installations/replacements: One (1)
 - 400 Eight St. E.

Backflow Preventer Installations/Replacements:

- Number of backflow preventer installations/replacements: One (1)
 - 400 Eight St. E.

Backflow Prevention - Testing:

- Number of backflow preventers tested: Two (2)
 - 400 Eight St. E. and 555 Flinder's Ave.

Other Information:

- Summarized final costs for invoicing of private works associated with private works
- Recorded locations of curb stops at various locations.
- Performed connection inspection of water service at 844 Huffman Crt.
- Continued with locates (as required) of the Town's infrastructure for various Contractors/Utility Companies.
- Continued with the valve exercising program (Area 5)
- Worked in conjunction with Bay City Contracting to disinfect and test water quality before putting the new water main back into service (Phair Avenue - Third St. E. to Sixth St. E.).
- Worked in conjunction with Makkinga Contracting to disinfect and test water quality before putting the new water main back into service (Colonization Rd. E. - Third St. E. to Fifth St. E.).

WATER TREATMENT PLANT:

- July, 2016 - In receipt of the Water Treatment Facility Monthly Report.

SEWERAGE COLLECTION:

Wastewater Main Backups:

- Number of wastewater main backup: None

Wastewater Main Repairs:

- Number of wastewater main repairs: None

Wastewater Manhole Repairs:

- Number of wastewater manhole repairs: One (1)
 - In front of 732 Church St.

Sewer Service Breaks:

- Number of sewer service breaks: Two (2)
- 626 Church St. and 953 Russell Bay

Sewer Service Repairs:

- Number of sewer service repairs: One (1)
- 1311 Emo Rd.

Sewer Service Installations (NEW):

- Number of sewer service installations: Five (5)
- Nelson Street (600 blk.) - Town House (Five Services)

Sewer Service Terminations:

- Number of water service terminations: None

Other Information:

- Cleaned nine (9) plugged sewer services at the following locations:
 - 626 Church St. (2), 720 Nelson St., 413 Mosher Ave., 631 Church St., 925 Phair Ave., 544 Webster Ave.
 - 831 Phair Ave. and 316 Second St. E.
- CCTV inspected various building sewer services.
- Performed connection inspection of sanitary service at 844 Huffman Crt.
- Traced various building sewer services.
- Completed locates (as required) of the Town's infrastructure for various Contractors/Utility Companies.
- Recorded locations of cleanouts at various locations.

WASTE-WATER TREATMENT FACILITY:

- July, 2016 - In receipt of the Wastewater Treatment Facility Monthly Report
- Kingdom Construction Ltd. on site - Dewatering and screen upgrades.

WASTE MANAGEMENT:

Garbage Collection:

- Number of complaints regarding garbage collection:
 - Town - 0 complaints, Asselin's - 4 complaints

Sanitary Landfill (Waste Disposal Site):

Landfill Scales functioning properly during this period.

- Amount of residential waste delivered to the landfill:
 - 208,560 kgs (206.65 tonnes)
- Amount of ICI waste delivered to the landfill:
 - 400,730 kgs (400.73 tonnes)
- July, 2016 - Hauled material from construction project to landfill - cover garbage.

Recycling:

- Number of complaints regarding recycled materials:
 - Town - 0 complaints, Asselin's - 1 complaint
- Amount of recycled waste diverted from the landfill:
 - No Data - Emterra Environmental

Prepared By: _____ Environmental & Facilities Superintendent

Date: _____