

MSC Work Orders

ID	Origin ID	Asset ID	Department	Work Order Type	Work Order Subtype	Asset Name	Asset Location	Status	Hours	All Notes	Completed Date	Actual Cost
WO-2689			Com Serv - MSC	General Maintenance - MSC				Completed	2	IFK Roof Snow Removal.	3/14/2019	\$58.58
WO-2642			Com Serv - MSC	General Maintenance - MSC				Completed	1	Install floor mount UPS cabinet.	3/7/2019	\$29.29
WO-2641	PM-2811	15286	Com Serv - MSC	Preventative Maintenance - MSC	Chiller Drian	52 Chiller	52 Ice Plant	Completed			3/14/2019	
WO-2633	PM-2801	15286	Com Serv - MSC	Preventative Maintenance - MSC	Chiller Drian	52 Chiller	52 Ice Plant	Completed			3/7/2019	
WO-2572	PM-2759	15266	Com Serv - MSC	Preventative Maintenance - MSC	Filter Backwash	Pool Sand Filters #2	Main Floor Pool Mechanical Room	Completed			3/19/2019	
WO-2558	PM-2748	15265	Com Serv - MSC	Preventative Maintenance - MSC	Filter Backwash	Pool Sand Filters #1	Main Floor Pool Mechanical Room	Completed			3/8/2019	
WO-2556	PM-2746	15278	Com Serv - MSC	Preventative Maintenance - MSC	52 Rink Boiler Inspection	52 Rink Boiler	52 Lobby Furnace Room	Completed		bled 3 valves checked hot water tank ok	3/6/2019	
WO-2555	PM-2745	15276	Com Serv - MSC	Preventative Maintenance - MSC	Chiller Drian	Chiller	IFK Ice Plant	Completed			3/1/2019	
WO-2554	PM-2744	15286	Com Serv - MSC	Preventative Maintenance - MSC	Chiller Drian	52 Chiller	52 Ice Plant	Completed			3/6/2019	
WO-2405	PM-2539	21058	Com Serv - MSC	Preventative Maintenance - MSC	Condensor Inspection	Condensor Water Tank	52 Ice Plant	Completed			3/14/2019	