

Workorder Summary Report

Report Start Date: Oct 1, 2021 12:00 AM
Report End Date: Oct 31, 2021 11:59 PM
Location: 1103*
Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM
Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
2481074			1103, Fort Frances WPCP	OPER	Inspection	1	MONTHS	Snow Removal at Wastewater Treatment (1m) 1103	COMP	10/1/21 12:00 AM	11/5/21 11:02 AM	11/5/21 11:02 AM	
2481079			1103, Fort Frances WPCP	OPER	Inspection	1	MONTHS	Grass Cutting at Wastewater Treatment (1m) 1103	COMP	10/1/21 12:00 AM	11/5/21 11:03 AM	11/5/21 11:03 AM	
2493553	0000227376	PANEL ALARM/DIALER	1103, Fort Frances WPCP, Process, Process Control & Monitoring	PM	Inspection	1	MONTHS	Critical Alarm/Dialer Testing (1m) 1103	COMP	10/1/21 12:00 AM	10/28/21 11:00 AM	10/28/21 12:00 PM	Dialer Test -We test every day.
2493557			1103, Fort Frances WPCP	PM	Refurbish/Replace/Repair	1	MONTHS	Diesel Gensets Inspection/Functional Tests (1m) 1103	COMP	10/1/21 12:00 AM	10/22/21 08:02 AM	10/22/21 08:02 AM	Diesel Gensets Inspection/Functional Tests (1m) 1103 -Wajax did load testing on all lift station gensets this month. The portable diesel genset is still scheduled for replacement by the town this year.
2493573			1103, Fort Frances WPCP	PM	Health and Safety	1	MONTHS	Health And Safety Inspection (1m) 1103	COMP	10/1/21 12:00 AM	10/26/21 10:00 AM	10/26/21 11:00 AM	H&S Inspection -This month I'd like to add the plow truck as the box has extensive rust and shouldn't be entered.
2493584			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	TPM Inspection/Maintenance (1m) 1103	COMP	10/1/21 12:00 AM	11/5/21 11:02 AM	11/5/21 11:02 AM	
2493905			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	Blowers/Motors Inspection/Service (1m/3m) 1103	COMP	10/1/21 12:00 AM	10/29/21 09:15 AM	10/29/21 10:15 AM	
2493913	0000246402	CENTRIFUGE GS2-2-1 TEACUP/GRIT SNAIL	1103, Fort Frances WPCP, Process, Primary Treatment, Primary Sludge Degritting	PM	Inspection	1	MONTHS	Teacup Centrifuge Inspection/Service (1m/3m/1y) 1103	COMP	10/1/21 12:00 AM	10/26/21 08:00 AM	10/26/21 09:00 AM	Teacup Maint. -I removed the lid and found little debris.
2494555	0000129929	ANALYZER A1C1-1 HEADWORKS GAS	1103, Fort Frances WPCP, Process, Process Control & Monitoring, Headworks	PM	Calibration	6	MONTHS	Analyzer Gas Calibration (6m) 1103	COMP	10/1/21 12:00 AM	10/22/21 08:06 AM	10/22/21 08:06 AM	Analyzer Gas Calibration (6m) 1103 -This was just done in September. All okay
2494558			1103, Fort Frances WPCP	PM	Inspection	1	YEARS	UPS Inspection/Replacement (1y) 1103	COMP	10/1/21 12:00 AM	10/8/21 06:51 AM	10/8/21 06:51 AM	

Workorder Summary Report

Report Start Date: Oct 1, 2021 12:00 AM

Report End Date: Oct 31, 2021 11:59 PM

Location: 1103*

Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM

Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
2498995	0000246436	PANEL CONTROL PCL	1103, Boundary Pumping Station, Facility	CALL	Refurbish/ Replace/Repair	0		Boundary Road high level alarm call back	COMP		10/7/21 11:10 PM	10/8/21 12:30 AM	Boundary Road high level alarm call back -I was called by the auto dialler for a Boundary Road lift station high level alarm at 2310 hours. Once at the plant I acknowledged and cleared the alarms on the SCADA computer. The level at the station was pumped down and the next pump cycle was normal.