

Workorder Summary Report

Report Start Date: Jan 1, 2018 12:00 AM

Report End Date: Jan 31, 2018 11:59 PM

Location: 1103\*

Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM

Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
<a href="#">629306</a>	0000129812	METER LEVEL MILLTRONIC EFFLUENT FLOW	1103, Fort Frances WPCP, Process, Process Control & Monitoring	CALL	REFURBISH/ REPLACE/ REPAIR	0		Plant Effleunt Alarm 1103	COMP		1/30/18 07:51 AM	1/30/18 07:58 AM	Plant Effluent Alarm -I arrived onsite to find the plants outfall to be excessive. I then checked SCADA and realized it was a false reading due to extreme cold weather. I then also completed a visual inspection and all was normal.
<a href="#">619953</a>			1103, Fort Frances WPCP	PM	HEALTH AND SAFETY	1	MONTHS	Health And Safety Inspection (1m) 1103	COMP	1/1/18 12:00 AM	1/30/18 08:07 AM	1/30/18 08:07 AM	Monthly Inspection -Still some outstanding construction issues.
<a href="#">620375</a>			1103, Fort Frances WPCP	PM	INSPECTION	1	MONTHS	Blowers/Motors Inspection/Service (1m/3m) 1103	COMP	1/1/18 12:00 AM	1/30/18 08:05 AM	1/30/18 08:05 AM	Monthly Blower Maint. -I greased all blowers and inspected air filters.
<a href="#">620383</a>	0000246402	CENTRIFUGE GS2-2-1 TEACUP/ GRIT SNAIL	1103, Fort Frances WPCP, Process, Primary Treatment, Primary Sludge Degritting	PM	INSPECTION	1	MONTHS	Teacup Centrifuge Inspection/ Service (1m/3m/1y) 1103	COMP	1/1/18 12:00 AM	1/26/18 03:31 PM	1/26/18 03:31 PM	Teacup Centrifuge Inspection/ Service (1m/3m/1y) 1103 -The teacup was drained for inspection. There was no debris found and the snail was drained and hosed for inspection. Lubrication was completed.