

Workorder Summary Report

Report Start Date: Jul 1, 2021 12:00 AM

Report End Date: Jul 31, 2021 11:59 PM

Location: 1103*

Work Order Type: ADMIN,CALL,CAP,CORR,EMER,OPER,PM

Work Order Class:

				WorkOrder		PM Schedule		Workorder Details					
WO #	Asset ID	Asset Description	Location Description	Type	Class	FEQ	Units	Work Order Description	Status	Schedule Start	Actual Start	Actual Finsh	WorkLog Detail
2343743			1103, Fort Frances WPCP	OPER	Inspection	1	MONTHS	Grass Cutting at Wastewater Treatment (1m) 1103	COMP	7/1/21 12:00 AM	8/9/21 07:47 AM	8/9/21 07:47 AM	
2355214	0000227376	PANEL ALARM/DIALER	1103, Fort Frances WPCP, Process, Process Control & Monitoring	PM	Inspection	1	MONTHS	Critical Alarm/Dialer Testing (1m) 1103	COMP	7/1/21 12:00 AM	7/31/21 11:00 AM	7/31/21 12:00 PM	Dialer Test -We test daily
2355218			1103, Fort Frances WPCP	PM	Refurbish/Replace/Repair	1	MONTHS	Diesel Gensets Inspection/Functional Tests (1m) 1103	COMP	7/1/21 12:00 AM	7/23/21 03:45 PM	7/23/21 03:45 PM	Diesel Gensets Inspection/Functional Tests (1m) 1103 -exercised gensets at lift stations and portable Yamaha. Portable diesel is scheduled for replacement by the Town of Fort Frances. KC
2355234			1103, Fort Frances WPCP	PM	Health and Safety	1	MONTHS	Health And Safety Inspection (1m) 1103	COMP	7/1/21 12:00 AM	7/31/21 06:45 AM	7/31/21 07:45 AM	H&S Inspection -No issues
2355245			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	TPM Inspection/Maintenance (1m) 1103	COMP	7/1/21 12:00 AM	8/9/21 07:46 AM	8/9/21 07:46 AM	
2355579			1103, Fort Frances WPCP	PM	Inspection	1	MONTHS	Blowers/Motors Inspection/Service (1m/3m) 1103	COMP	7/1/21 12:00 AM	7/31/21 01:52 PM	7/31/21 01:52 PM	Monthly Blowers -I greased all blowers and changed oil in blower 5.
2355587	0000246402	CENTRIFUGE GS2-2-1 TEACUP/GRIT SNAIL	1103, Fort Frances WPCP, Process, Primary Treatment, Primary Sludge Degritting	PM	Inspection	1	MONTHS	Teacup Centrifuge Inspection/Service (1m/3m/1y) 1103	COMP	7/1/21 12:00 AM	7/24/21 02:14 PM	7/24/21 02:14 PM	Teacup Centrifuge Inspection/Service (1m/3m/1y) 1103 -Drained and inspected teacup, no debris. Lubricated bearings and drive chain grit snail. KC
2364941	0000246415	TANK PROCESS CLARIFIER SECONDARY CELL #2	1103, Fort Frances WPCP, Process, Secondary Treatment	CALL	Refurbish/Replace/Repair	0		Long Collector #2 Failure 1103	COMP		7/27/21 07:44 AM	7/27/21 07:52 AM	Long Collector #2 Failure -I arrived onsite to find the shear pin to have broken so I replaced it with a new one and monitored the drive for 10 minutes.